

University of Missouri – Kansas City

CRR 110.015 Facilities Needs and Reporting

CRR 110.015 was established to keep the facilities of the University of Missouri system in good condition to ensure the needs of the University's education and research missions are met. CRR 110.015 requires an annual investment to maintain a Campus Facilities Condition Needs Index (FCNI) of 0.30 or lower for Education and

Bloch Heritage Hall	Bloch Heritage Hall Renovation	\$13,295,497
Bloch Heritage Hall	Marion H. Bloch Terrace & Park	\$194,231
Cockefair Hall	Cockefair Hall HVAC Upgrades	\$182,959
Cooling Plant	Central Cooling Electrocell	\$314,711
Dental School	SOD Fire Pump	\$173,776
Fine Arts	Fine Arts Photography Studio	\$140,361
Flarsheim Hall	Flarsheim Hall Fume Hood Retro	\$408,017
Medical School	SOM 3rd Fl Media Center Renov	\$199,206
Miller Nichols Library	MNL 3rd Floor Renovation	\$1,261,095
Olson Performing Arts Center	OPAC Lobby Ceiling Wtr Damage	\$330,015
Olson Performing Arts Center	OPAC Theatre Interior Doors Re	\$124,650
Olson Performing Arts Center	PAC & Grant Hall Renovations	\$548,645
Olson Performing Arts Center	PAC Ionization Devices for AHU	\$137,072
University Way	University Way Elevator Repair	\$112,633
Various	Campus Card Access 11 Bldgs	\$192,088
Various	Emer. Steam Ln Repair SH & MH	\$272,311
Various	UMKC Exterior Wayfinding	

